



Job Title:	Shakeout Laborer	Department:	Shakeout
Reports to:	Foundry Manager	Travel Required:	none
Level/Salary Range:	\$10.00-\$13.00/Hr	Position Type:	Permanent
HR Contact:	Missy Miedema	Date Posted:	8/5/2016
Will Train Applicant(s):	yes	Posting Expires:	When filled
Applications Accepted By:			
FAX OR EMAIL: Ray@russelloyfoundry.com		MAIL: Russelloy Foundry Attn: Ray Cole 1005 4 th Street Durant, IA 52747	
Job Description			
<p>ESSENTIAL JOB REQUIREMENTS</p> <ol style="list-style-type: none"> 1. Push molds down gravity conveyor approximately 1000lbs-3000lbs 2. Take molds to hoist to vibrating shakeout 3. Stack flasks and remove casting from shaker 4. Swing sledgehammer accurately 5. Lift up to 50 LBS. 6. Stand on feet 8 hours <p>QUALIFICATIONS AND EDUCATION REQUIREMENTS</p> <p>OPEN</p> <p>LIMITATIONS AND DISCLAIMER</p> <p>THE ABOVE JOB DESCRIPTION IS MEANT TO DESCRIBE THE GENERAL NATURE AND LEVEL OF WORK BEING PERFORMED; IT IS NOT INTENDED TO BE CONSTRUED AS AN EXHAUSTIVE LIST OF ALL RESPONSIBILITIES, DUTIES, AND SKILLS REQUIRED FOR THE POSITION.</p>			



All job requirements are subject to possible modification to reasonably accommodate individuals with disabilities. Some requirements may exclude individuals who pose a direct threat or significant risk to the health and safety of themselves or other employees.

This job description in no way states or implies that these are the only duties to be performed by the employee occupying this position. Employees will be required to follow any other job-related duties requested by their supervisor in the compliance with Federal and State Laws.

Requirements are representative of minimum levels of knowledge, skills and/or abilities. To perform this job successfully, the employee must possess the abilities or aptitudes to perform each duty proficiently. Continuous employment remains on an "at-will" basis.

Manager's Name

Title

Manager's Signature

Date

Human Resources Approval/Comment:

Authorized Human Resources Signature

Date